



State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:					
OGM	Joe Helfrich Environmental Scientist III				
Company	Layne D. Jensen Environmental Engineer				
Company	Dennis Ware Controller				

Inspection Report

Permit Number:	C0070038			
Inspection Type:	PARTIAL			
Inspection Date:	Tuesday, April 11, 2006			
Start Date/Time:	4/11/2006 9:30:00 AM			
End Date/Time:	4/11/2006 2:30:00 PM			
Last Inspection:	Thursday, March 16, 2006			

Inspector: Joe Helfrich, Environmental Scientist III

Weather: cool, partly cloudy, 50 InspectionID Report Number: 922

Accepted by: whedberg

Wednesday, April 12, 2006

Date

4/14/2006

Permitee: PLATEAU MINING CORP Operator: PLATEAU MINING CORP

Site: WILLOW CREEK MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	14,662.49	
Total Disturbed	154.05	
Phase I		
Phase II		
Phase III		

Mineral Ownership

Types of Operations Federal ✓ Underground State Surface ✓ Loadout County Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The purpose of this site visit was to conduct a partial inspection of the Willow creek reclaimed area. The inspection focused on evaluating the vegetation required to control erosion for reclaimed areas slated for an alternative postmining land use. The College of Eastern Utah has expressed an interest in the buildings and a portion of Plateau Mining Corporation's property to be used as a training facility. The Utah Board of Regents is scheduled to review the proposed purchase agreement between the College of Eastern Utah and Plateau Mining Corporation on April 21st of 2006. Once the agreement is approved, the Company will submit an application to the Division for phase III bond release. Public notification will begin on Thursday, April 11, 2006.

Inspector's Signature:

Helfrich, Environmental Scientist III

Inspector ID Number: 1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070038 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 11, 2006

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		~	
2.	Signs and Markers	V		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	✓		V	
13.	Revegetation	✓		✓	
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.Ł	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070038 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 11, 2006

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

Phase 1 bond release of the Schoolhouse Refuse site (45.6 acres) and Phase III bond release of the Price River Water Improvement District (PRWID), 46.2 acres has been reviewed under Task ID #2424. The information was previously reviewed under Task ID #2344. There are 1.2 acres in Barn Canyon that were not disturbed.

2. Signs and Markers

Signs with the required information were posted at the entrances to the reclaimed areas.

12. Backfilling And Grading

Final reclamation efforts are underway at the rail loadout facility. At the time of this inspection, a trackhoe with a pneumatic hammer attachment was observed demolishing the cement pad. Photographs were taken.

13. Revegetation

The slopes behind the shop and warehouse were evaluated for stability and vegetative cover required to control erosion. The area approximately 20' wide x 50' long that had shown some minor soil movement along the surface has remained stable since it was first noted on a previous inspection dated January 26, 2005. Additional seeding is recommended for this area in conjunction with the next precipitation event. The entire area was reclaimed, surface roughened and seeded in 2004. Since that time, the slopes have been exposed to numerous precipitation events and two seasons of snow melt exhibiting very minor sediment deposition that remains at the toe of the slopes. This is due in part to the surface roughening and cover material along the 65% slopes. The slopes have been inspected on the average of once every two months since they have been reclaimed, indicating no signs of weakness, failure, or structural instability. Layne Jensen, professional engineer from the Earthfax Engineering consulting firm, has evaluated the slopes for stability as well. A copy of Mr. Jensen's findings will be included in the Phase III Bond Release application. Estimates of 40% rock, and 18% vegetative cover at this point in time appear to be more than adequate to control erosion. The sediment yield calculations for the reclaimed slopes indicate that the reclaimed areas can meet effluent limitations. However, the permittee has opted to retain the sediment pond for additional sediment control. Photographs were taken.